

EWS357-FIT

EnGenius FIT Wi-Fi 6 2x2 Dual-band Indoor Access Point

v1.0.50

- Support wireless client mac-based WMM
- Traffic log includes NAT information when logged to the syslog server.
- Prevent DNS resolved fail.
- Support application DSCP tagging.
- Fix Command Injection Vulnerabilities.

v1.0.40

- Supports multiple languages of system name in LSP.
- Update the style of the LSP/Standalone web GUI.
- Fingerprint supports more OS types.
- Fixed AP offline caused by UTF8 decode of device name.
- Fixed the certificates sometimes disappear after device firmware upgrade.
- Supports website filtering.
- Supports PSTI certification requirements.

v1.0.30

- Fixed Fit AP sometimes not displaying Wi-Fi usage information in FitXpress.
- Fixed Fit AP sometimes appearing offline in FitXpress.
- Fixed an issue where enabling WDS in station mode would cause VLAN passthrough to fail.
- Fixed an issue where the MAC filter white list does not working in standalone mode.
- Fixed the issue where the web GUI turned into LSP and devices couldn't be found in 'Inventory -> Pending Approval' after upgrading the firmware from v1.0.1 in standalone mode.

v1.0.22

- Fixed captive portal splash page redirect issue when managed by Fit controller.
- Resolved AP offline issue with Fit controller after firmware upgrade from v1.0.4.
- Remove email alert: "ezmcloud configuration change notification" in standalone mode.

v1.0.21

- Support MAP LED behavior at MAP listen mode.
- Change minimum TX power to 7 in standalone mode.

v1.0.20

- Support Repeater function in standalone mode only.
- Support "Isolate Ethernet Devices" advanced setting for guest network in standalone mode only.

v1.0.10

- Support FitRegister service.

v1.0.4

- Fixed the AP can not re-connect to FitCon server after network down/up.