

Release Notes

EXT1105P

Ver. v1.0.11-001(1.1.9)

Revision History

Revision	Date	Reason of Changes
v1.0.11-001(1.1.9)	Dec 1, 2023	Fix update

Change Log

F/W Version	v1.0.11-001(1.1.9)
Type	Description
New Feature	N/A
Change	N/A
Fix	1. Enclosed fix for the incorrect front port LED blinking, when pressing Led Blinking button on the cloud.