

# **Release Notes**

**EXT1106**

**Ver. v1.0.11-2(1.2.7)**

# Revision History

Revision	Date	Reason of Changes
v1.0.11-2(1.2.7)	Nov 23, 2023	Fix update

# Change Log

F/W Version	v1.0.11-2(1.2.7)
Type	Description
New Feature	N/A
Change	N/A
Fix	1. Enclosed fix for the incorrect front port LED blinking, when pressing Led Blinking button on the cloud.